

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_140702_04

LOKASI: LABUHAN TANGGA KECIL

KECAMATAN: BANGKO KABUPATEN: ROKAN HILIR

PROVINSI : RIAU

DATA TABEL: JAM-JAMAN PADA HARI KAMIS, 28 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:03	-2.3	-2.3	-2.29	1.37	1.3	1.5	0	0	0	BAHAYA
01:00:07	-2.29	-2.3	-2.29	1.4	1.4	1.4	0	0	0	BAHAYA
02:00:06	-2.3	-2.3	-2.29	1.4	1.4	1.4	0	0	0	BAHAYA
03:00:06	-2.29	-2.3	-2.29	1.4	1.4	1.4	0	0	0	BAHAYA
11:30:04	-2.3	-2.3	-2.3	1.3	1.3	1.3	0	0	0	BAHAYA
12:00:00	-2.3	-2.3	-2.3	1.35	1.3	1.4	0	0	0	BAHAYA
13:00:06	-2.3	-2.3	-2.3	1.42	1.4	1.5	0	0	0	BAHAYA
14:00:01	-2.3	-2.3	-2.3	1.32	1.3	1.4	0	0	0	BAHAYA
15:00:06	-2.3	-2.3	-2.3	1.3	1.3	1.3	0	0	0	BAHAYA
16:00:06	-2.3	-2.3	-2.3	1.35	1.3	1.4	0	0	0	BAHAYA
17:00:05	-2.3	-2.3	-2.3	1.33	1.3	1.4	0	0	0	BAHAYA
18:00:05	-2.3	-2.3	-2.3	1.37	1.3	1.4	0	0	0	BAHAYA
19:00:03	-2.3	-2.3	-2.29	1.42	1.3	1.6	0	0	0	BAHAYA
20:00:01	-2.3	-2.3	-2.29	1.38	1.3	1.4	0	0	0	BAHAYA
21:00:00	-2.3	-2.3	-2.3	1.38	1.3	1.4	0	0	0	BAHAYA
22:00:02	-2.29	-2.3	-2.29	1.35	1.3	1.4	0	0	0	BAHAYA
23:00:03	-2.3	-2.3	-2.3	1.3	1.1	1.4	0	0	0	BAHAYA

http://sipalaga.brg.go.id