

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : OKI2

LOKASI : SIMPANG TIGA
KECAMATAN : TULUNG SELAPAN
KABUPATEN : OGAN KOMERING ILIR
PROVINSI : SUMATERA SELATAN

DATA TABEL: JAM-JAMAN PADA HARI RABU, 27 FEBRUARI 2019

Jam	Ground Water Level (meter)			Soil Moisture (%)			Curah Hujan (mm)			Status
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
00:00:00	0.03	0.02	0.03	10.4	10.32	9.8	0	0	0	AMAN
01:00:00	0.03	0.03	0.03	10.36	10.06	10.76	0	0	0	AMAN
02:00:00	0.03	0.03	0.04	10.38	10.19	9.93	0	0	0	AMAN
03:00:00	0.03	0.03	0.03	9.69	10.12	10	0	0	0	AMAN
04:00:00	0.03	0.03	0.03	9.33	10.06	9.34	0	0	0	AMAN
05:00:00	0.03	0.03	0.03	9.58	10.06	9.74	0	0	0	AMAN
06:10:00	0.03	0.03	0.03	9.95	10.32	9.93	0	0	0	AMAN
07:00:00	0.03	0.02	0.03	10.29	10.32	9.8	0	0	0	AMAN
08:00:00	0.03	0.02	0.04	9.89	10.32	9.74	0	0	0	AMAN
09:00:00	0.04	0.04	0.04	9.98	10.32	9.47	0	0	0	AMAN
10:00:00	0.05	0.04	0.05	10.57	10.32	11.01	0	0	0	AMAN
11:00:00	0.06	0.05	0.06	10.33	10.19	10.44	0	0	0	AMAN
12:00:00	0.06	0.06	0.06	10.12	10.12	10.12	0	0	0	AMAN

http://sipalaga.brg.go.id