

BADAN RESTORASI GAMBUT

REPUBLIK INDONESIA

STASIUN : BRG_621103_04 LOKASI : BUKIT RAWI

KECAMATAN: KAHAYAN TENGAH KABUPATEN: PULANG PISAU

PROVINSI: KALIMANTAN TENGAH

DATA TABEL: JAM-JAMAN PADA HARI SABTU, 02 MARET 2019

Jam	Ground Water Level (meter)			Soil Moisture (°/ _o)			Curah Hujan (mm)			Ctatus
	Rataan	Min	Max	Rataan	Min	Max	Komposit	Min	Max	Status
02:00:38	-0.02	-0.02	-0.02	71.4	71.4	71.4	0	0	0	SIAGA
11:50:36	-0.01	-0.01	-0.01	71.4	71.4	71.4	0	0	0	SIAGA
12:00:11	-0.01	-0.01	-0.01	71.34	71.1	71.4	0	0	0	SIAGA
13:00:09	-0.01	-0.01	-0.01	71.28	71.1	71.5	0	0	0	SIAGA
14:00:08	-0.01	-0.02	-0.01	71.27	71.2	71.4	0	0	0	SIAGA
15:00:59	-0.01	-0.01	-0	71.23	71.1	71.3	0.4	0	0.4	SIAGA
16:10:44	-0.01	-0.01	-0.01	71.1	71.1	71.1	0	0	0	SIAGA
17:00:22	-0.01	-0.01	-0	71.1	71.1	71.1	0	0	0	SIAGA
18:10:27	-0.01	-0.01	-0.01	71.1	71.1	71.1	0	0	0	SIAGA
19:20:12	-0.01	-0.01	-0.01	71	71	71	0	0	0	SIAGA
20:50:02	-0.01	-0.01	-0.01	71.1	71.1	71.1	0	0	0	SIAGA
21:00:08	-0.01	-0.01	-0.01	71.17	71.1	71.3	0	0	0	SIAGA
23:10:39	-0.01	-0.01	-0.01	71.25	71.2	71.3	0	0	0	SIAGA

http://sipalaga.brg.go.id