

|   |            |
|---|------------|
| Project   | Zen Plan B |
| Location  | Stef       |
| Submitted By  | 2          |
| Formwork deck fully complete with no gaps or holes  | Yes        |
| All decking panels and formwork sheets firmly secured   | No         |
| Edge boards complete and firmly secured   | N/A        |
| Edge protection in place and adequate   | Yes        |
| Scaffold and perimeter safety screens in place with no gaps   | No         |
| Deck fully extends to edge of scaffold  | N/A        |
| Hand railing complete, firmly fixed and of adequate strength  | N/A        |
| Steel safety mesh installed in all service penetrations   | No         |
| All penetrations covered, secured and clearly stencilled  | No         |
| Soffit surveyed   | Yes        |
| Fencing/cordons in place in areas not ready for handover  | No         |
| Required signage in place in areas not ready for handover   | Yes        |
| Safe access available for other trades at entry points of deck  | No         |
| Slip/trip hazards removed (excess materials, timber etc.)   | N/A        |
| Deck swept and cleaned of all debris  | No         |
| Engineer Sign off   | No         |
| Comments  | TEST       |
| The submitter of this report has confirmed that the specified deck is safe to use and is structurally adequate to support site personnel and design working loads (structural certificate to be provided by structural engineer prior to pour). |            |
| The person who has verified this report has confirmed the deck has been inspected to ensure that all required actions and controls have been implemented.   |            |
| Verified By   | Test       |
| Verified On   | 9-May-2016 |

Photos On Next Page.....

## PHOTOS

