

Project	Zen Plan B
Submitted On	10-May-2016 09:29PM
Location	Test
Submitted By	Patrick Noonan
Pour No	12
Stairmaster correct position	Yes
Edge boards braced	No
Centre of stairmaster flights propped	Yes
Pins and props	No
Z Bars in walls tight	Yes
Stairs cleaned	Yes
The submitter of this report has confirmed that the specified stairs are safe to use and are structurally adequate to support site personnel and design and working loads (structural certificate to be provided by structural engineer prior to pour).	
The person who has verified this report has inspected the Stairs and confirms that all required actions and controls have been implemented.	
Verified By	Test

Photos On Next Page.....

