


Frequency.of.O&M - attrapp.score 1




Temperature.range - attrapp.score 1




Flooding – attrapp.score 0.0082337894543772/ehicular.access – attrapp.score 0.94253363656







Slope - attrapp.score 0.995254702612684




Groundwater.depth - attrapp.score 1



Excavation - attrapp.score 1





Population.density - attrapp.score 1




solidsfree.sewer, Katarniya - techapp.score 0.653625296695099

onstruction.skills - attrapp.score 0.4925392276 Design.skills - attrapp.score 0.8199238413414







O&M.skills - attrapp.score 0.91643388972928




Management - attrapp.score 0.594



Pipe.supply - attrapp.score 1



Concrete.supply - attrapp.score 1



Spare.parts.supply - attrapp.score 1

