





Frequency.of.O&M – attrapp.score 1




emperature.range – attrapp.score 0.80269199141




Vehicular.access – attrapp.score 0.93877984526




Groundwater.depth – attrapp.score 0.9784457058




Excavation – attrapp.score 1







Population.density – attrapp.score 1



Construction.skills – attrapp.score 1



Design.skills – attrapp.score 1**O&M.skills – attrapp.score 1****Management – attrapp.score 0.906****Spare.parts.supply – attrapp.score 1****Surface.area.onsite – attrapp.score 1**