





Frequency.of.O&M – attrapp.score 1




temperature.range – attrapp.score 0.91237731796




Flooding – attrapp.score 0.008242892218286 vehicular.access – attrapp.score 0.94548805539




Slope – attrapp.score 0.0955000592825268




Groundwater.depth – attrapp.score 1









Excavation – attrapp.score 1



Construction.skills – attrapp.score 1



Design.skills – attrapp.score 1**O&M.skills – attrapp.score 1****Management – attrapp.score 0.091****Concrete.supply – attrapp.score 1****Spare.parts.supply – attrapp.score 1****Surface.area.offsite – attrapp.score 1****population.change.rate – attrapp.score 1**