


#### Frequency.of.O&M - attrapp.score 1




## Temperature.range - attrapp.score 1





# Flooding - attrapp.score 0.0080594939290077Vehicular.access - attrapp.score 0.89395810349






# Slope – attrapp.score 0.967129035612076 iroundwater.depth – attrapp.score 0.99665791580






#### Excavation – attrapp.score 1

# onstruction.skills - attrapp.score 0.4740479499







#### conventional.sewer, Katarniya - techapp.score 0.537341196008232


## Design.skills - attrapp.score 0.8238940429220

## O&M.skills - attrapp.score 0.64251249494993







Management - attrapp.score 0.096



Pipe.supply - attrapp.score 1



Concrete.supply - attrapp.score 1



Spare.parts.supply - attrapp.score 1

