

QHSE Inspection Report

Robot ID: QHSE-ROBOT-BETA-01
Timestamp: 2026-07-13T19:18:08.334207
Inspection Status: FAIL
Max Risk Level Flagged: Medium

element		confidence_score	risk_assessment	corrective_action
Tripping Hazard / Foreign Object Debris		94.46	Medium	Clear pathway immediately
	mouse	64.14	Low	None
	dining table	32.43	Low	None