बाढ तथा पहिरो अवस्था प्रतिवेदन

क्षेत्र र घटनाको मिति: 2026-08-26 | 85.30, 28.10, 85.42, 28.20

नक्साबाट प्राप्त नतिजा

	कडा	डिफल्ट	विस्तृत
पहिचान क्षेत्र (हेक्टर)	25.62	28.47	73.77
भित्रका भवन	73	84	167
नजिकका भवन	79	83	65
पहिचानसँग प्रतिच्छेद सडक (किमी)	2.69	3.16	6.09
पहिचान नजिकका पुल	3	4	6
प्रभावित बस्ती	1	1	1
सम्पर्कविच्छेद बस्ती	1	1	1
कमजोर पहुँच भएका बस्ती	38	38	38
मूल्याङ्कन गर्न नसकिने बस्ती	66	66	66

बस्तीको पहुँच

सबै परिदृश्यमा पहुँचविहीन बस्ती: स्याप्रु बेसी

1. स्याप्रु बेसी

विश्वसनीयता र सीमाहरू

अप्टिकल विश्वसनीयता: adequate. वैध अप्टिकल पिक्सेल: 86.9%.

No new-water or disturbed-surface detections in the radar classification.


नक्साका क्षेत्रहरू पहिचान हुन्, स्थल-सत्य होइनन्।


प्रयोग गरिएका तथ्याङ्क

2026-08-12, 2026-10-01

- Copernicus Data Space Sentinel-1 GRD via Sentinel Hub Process API
- Copernicus Data Space Sentinel-2 L2A via Sentinel Hub Process API
- Sahayak run selection metadata

नक्साबाट प्राप्त नतिजा





- Contains modified Copernicus Sentinel data 2026.
- Produced using Copernicus WorldDEM-30 © DLR e.V. 2010-2014 and © Airbus Defence and Space GmbH 2014-2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
- © OpenStreetMap contributors (ODbL). Any published modified OSM data stays under ODbL.
- Educational prototype, not an operational tool.