


Round changes




iPad

09:04 AM

inspecting

<




Appartementen Molukkenstraat
Groningen

☰

Plans

Tasks

Rounds




Begane grond DO-101

45 tasks

25 created

8 started

12 completed




1e verdieping DO-102

45 tasks

25 created

8 started

12 completed




2e verdieping U0-103

45 tasks

25 created


8 started

12 completed



+

Plattegrond (pdf/png/jpg)



Round pause

iPad

09:04 AM


<

Appartementen Molukkenstraat
Groningen

Assessment

|

Changes

 [download report](#)

Q

Resume inspection

1 Algemene indruk

Goed

2 Stand van het werk

- Casco is gereed
- Gevelmetselwerk loopt
- Albouw loopt, verloopingen in 2e verd. zijn voorziet van afwerkdoelen

3 Gemaakte audits afgelopen week

- Dakbedekking
- Tegelwerk
- Stucadoorswerk
- Cellenbeton

4 Te maken/af te ronden audits volgende weken

- Stalwerk metselwerk
- Metselwerk
- Hout beknopten 2e en 3e ault.
- Afwerkdoelen

*NB volgende rondgang audit nalaten

5 Volgende rondgang

- 13-11-2018

6 Algemeen, afspraken

- Vandaag rondgang gedaan samen met J.R. Kuisman van het. Aandachtspunten zijn verwerkt in el verslag. De aandachtspunten zijn aangemerkt met "NB"

Algemene indruk kwaliteit installaties is positief

kan resumeren wanneer er
• nog geen volgende ronde
bestaat?
• het dezelfde dag is?