Inspection Photo Report 檢測照片報告

檢測照片報告					
Item No 設備編	號 F-1301	D	Plant 廠區 台肥苗栗廠	Inspected a 檢測時機	
Pipe N 管線編	0 號	P-1301	D-A1	Ins. Date 檢查日期	2024/07/22
	TO ALL TO ALL THE STATE OF THE			2	E1
Location	P-1301D-A1	Location	P-1301D-A1	Location	P-1301D-A1-E1
Description	N/A	Description	正常	Description	正常
☑Before □Af	ter Clearing Inspected By VT	☑Before □	After Clearing Inspected By VT	☑Before □ Af	ter Clearing Inspected By VT
	EZ EI		E		El
Location	P-1301D-A1-E2	Location	P-1301D-A1-E3	Location	P-1301D-A1-E4
Description	正常	Description	正常	Description	正常
	ter Clearing Inspected By VT		After Clearing Inspected By VT		ter Clearing Inspected By VT
	6.4				
Location	P-1301D-A1-T1	Location	P-1301D-A1-T2	Location	
Location Description	P-1301D-A1-T1 正堂	Location	P-1301D-A1-T2 正学	Location Description	
Description	P-1301D-A1-T1 正常 eter Clearing Inspected By VT	Description	P-1301D-A1-T2 正常 After Clearing Inspected By VT	Description	fter Clearing Inspected By
Description ☑Before □Af Location	正常	Description Before Location	正常	Description Before A	fter Clearing Inspected By
Description ☑Before □Af Location Description	正常	Description Before Location Description	正常	Description Before At Location Description	fter Clearing Inspected By fter Clearing Inspected By