

Mechanical Permit Inspection Checklist

PERMIT

Permit No.	MES-2026-1187	Address	1523 S Alma School Rd, Mesa, AZ 85210
------------	---------------	---------	---------------------------------------

INSPECTION

Inspector Name	Ray Delgado
Inspector Badge No.	MSA-4471
Inspection Date	2026-08-27
Inspection Result	Approved with corrections
Re-inspection Fee	\$75

- ☒ Condensate drain trapped and terminated properly
- ☒ Disconnect within sight of unit
- ☐ Refrigerant line set insulated

Inspector

Contractor