

Work Order

No. WO-118776

CUSTOMER & VISIT

Customer	David Martinez		
Service address	8765 W Thunderbird Rd, Peoria, AZ 85381		
Date	2026-07-14	Technician	Carlos Rodriguez

EQUIPMENT

Serial No.	Model
SN-TRA-789012	XR15a

WORK PERFORMED
Replaced blower motor capacitor, tested airflow.

CHARGES

TOTAL	\$210
-------	-------