

Work Order

No. WO-118902

CUSTOMER & VISIT

Customer	James Mitchell		
Service address	4521 E Camelback Rd, Phoenix, AZ 85018		
Date	2026-08-28	Technician	Carlos Rodriguez

EQUIPMENT

Serial No.	Model
SN-LEN-567890	XP15

WORK PERFORMED
Seasonal checkup, washed condenser coil, verified airflow and refrigerant charge.

CHARGES

TOTAL	\$150
-------	-------

Technician

Customer acceptance