

Work Order

No. WO-119061

CUSTOMER & VISIT

Customer

Jennifer Lee

Service address

5600 W Camelback Rd, Glendale, AZ 85301

Date

2026-08-30

Technician

David Chen

EQUIPMENT

Serial No.	Model
SN-LEN-345678	XC25

WORK PERFORMED

Compressor hard start kit installed, system tested under load.

CHARGES

TOTAL	\$540
-------	-------