

Sonoran Comfort Air
4410 E Baseline Rd, Mesa, AZ 85206
(480) 555-0199 | info@sonorancomfortair.com

INSPECTION REPORT

Date: 05/09/2026

Customer: Donna Sorensen

Service Address: 174 N College Ave, Phoenix, AZ 85001

Findings:

- Coil clean, no leaks found
- Refrigerant charge within spec

Technician: Kevin Pratt