



ENVIRONMENTAL INCIDENT REPORT - ROOSEVELT - PRODUCTION WATER SPILL

Report Taken By:	Kim Viehweg		
Date / Time Reported:	11/25/2022 18:0		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Dan Huber	Title:	
Company:	Javelin Energy Partners	Phone:	(435) 503-4058
Date & Time Discovered:	11/25/2022 15:10		

RESPONSIBLE PARTY

Name:	Javelin Energy Partners	Phone:	(435) 503-4058
Address:	17900 W 3750 N, Altamont, UT, 84001		

INCIDENT LOCATION

Incident Address:	lat/long 40.294804° N, -110.335807° W		
Nearest Town:	ROOSEVELT	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 556451 (N) 4460690	Land Ownership:	Private

INCIDENT SUMMARY

Caller reported a 39 barrel production water spill into a right-of-way sandy soil ditch on the side of the road that contained no water. He said the pipeline went from the following well locations: Hunt 1-24B4 to El Paso 3-21B4. No waterways were impacted. The soil will be flushed and tested. Spill location on attached map is approximate.

CHEMICAL(S) REPORTED

Production Water 39 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DEQ DE	Nathan Hall	11/25/2022	18:10	Kim Viehweg	Active
	Tri-County HD	Group	11/25/2022	18:40	Kim Viehweg	
	DOGM	Group	11/25/2022	18:40	Kim Viehweg	

ACTIONS TAKEN	Date	Agency	Action	Action Details
	5/8/2023	DEQ DE	Incident Closure	Informal note in database - Additional samples submitted after more cleanup, now meets the DWQ cleanup criteria.
	1/3/2023	DEQ DE	Report received	reviewed report of sampling after initial cleanup, results exceeded required levels