



ENVIRONMENTAL INCIDENT REPORT - ROOSEVELT - PRODUCTION WATER SPILL

Report Taken By:	Kim Viehweg		
Date / Time Reported:	11/28/2022 13:20		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Teisha Black	Title:	
Company:	XCL Resources	Phone:	(435) 724-3086
Date & Time Discovered:	11/24/2022 10:0		

RESPONSIBLE PARTY

Name:	XCL Resources	Phone:	(346) 335-1081
Address:	600 N. Shepherd Dr., Suite 390, Houston, TX, 77077		

INCIDENT LOCATION

Incident Address:	GPS: 40.31556, -110.19060		
Nearest Town:	ROOSEVELT	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 568765 (N) 4463121	Land Ownership:	Private

INCIDENT SUMMARY

Caller stated that one of their water haulers failed to show up on time and the tanks overfilled with production water and about 200 barrels spilled onto the soil. No waterways were impacted. They will extract as much water as they can from the spill site, then they will sample the soil and remove any contaminated soil and dispose of it properly. Spill location on attached map is approximate.

CHEMICAL(S) REPORTED

Production Water 200 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DEQ DE	Nathan Hall	11/28/2022	16:15	Kim Viehweg	Active
	Tri-County HD	Group	11/28/2022	16:20	Kim Viehweg	
	DOGM	Group	11/28/2022	16:20	Kim Viehweg	

ACTIONS TAKEN	Date	Agency	Action	Action Details
	12/23/2022	DEQ DE	Incident Closure	Informal note in database - spill did not leave the DOGM permitted pad secondary containment
	12/22/2022	DEQ DE	Site Visit	Evaluate Spill