



ENVIRONMENTAL INCIDENT REPORT - ☐

Report Taken By:			
Date / Time Reported:	6/14/2022 0:0		

REPORTING PARTY DATES AND TIMES

Reporting Party:		Title:	Field Regulatory Manager
Company:	XCL Resources	Phone:	
Date & Time Discovered:	6/12/2022 5:0		

RESPONSIBLE PARTY

Name:		Phone:	
Address:	157 S 300 E, Roosevelt UT		

INCIDENT LOCATION

Incident Address:			
Nearest Town:	- Please Select -	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 586942 (N) 4458049	Land Ownership:	Private

INCIDENT SUMMARY

The gasket between the fire tube and treater failed, and sprayed oil around the pad and into the agricultural field. Estimating a 4 bbl spill.

All oil has been cleaned up from the pad, and samples have been collected to ensure that the remedial action was complete on the pad. They are working with the landowner to create a plan for clean-up an assessment of the agricultural area.

CHEMICAL(S) REPORTED

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
-------------------	-------	-------------	----------	---------------	------------	----------	------------

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
-----------------------	--------	---------	------	------	----	---------

ACTIONS TAKEN	Date	Agency	Action	Action Details
---------------	------	--------	--------	----------------