



ENVIRONMENTAL INCIDENT REPORT - PRODUCTION WATER SPILL - ROOSEVELT

Report Taken By:	Morgan Atkinson		
Date / Time Reported:	8/18/2022 9:45		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Josh Morgan	Title:	
Company:	Uinta Wax Operating	Phone:	(817) 231-8756
Date & Time Discovered:	8/15/2022 8:0		

RESPONSIBLE PARTY

Name:	Uinta Wax Operating	Phone:	(817) 231-8756
Address:	5128 Apache Plume Road, Ft Worth, Texas 76109		

INCIDENT LOCATION

Incident Address:			
Nearest Town:	ROOSEVELT	County:	DUCHESNE
Highway:		Mile Marker:	
UTM:	(E) 538866 (N) 4455424	Land Ownership:	Private

INCIDENT SUMMARY

Caller is reporting a spill of production water from a ruptured Salt Water Disposal (SWD) line. 10 barrels of production water impacted the pad and surrounding soils. Contaminated soil has been removed by a crew with shovels and hauled to INW Disposal Facility. The line is being repaired and will be covered with clean soil if necessary.

No impacts to waterways, soli only.

Caller stated he will notify DOGM and BLM.

CHEMICAL(S) REPORTED

Production Water 10 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	Tri-County HD	Cindy	8/18/2022	09:50	MPA	
	DWQ	Danny Ryan	8/18/2022	09:50	MPA	Active
	BLM	Bill Civish	8/18/2022	09:55	Josh Morgan	
	DOGM	Staff	8/18/2022	09:45	Josh Morgan	



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 15812

ACTIONS TAKEN	Date	Agency	Action	Action Details
	1/5/2023	DEQ DE	Incident Closure	Informal note in database - meets DWQ quick site cleanup criteria
	8/22/2022	DWQ	DWQ No Enforcement	