



ENVIRONMENTAL INCIDENT REPORT - OURAY -- PRODUCED WATER SPILL

Report Taken By:	Kevin Okleberry		
Date / Time Reported:	7/21/2021 16:15		

REPORTING PARTY DATES AND TIMES

Reporting Party:	Grizz Oleen	Title:	EHS Field Lead
Company:	Caerus Oil and Gas	Phone:	(435) 790-9669
Date & Time Discovered:	7/20/2021 21:0		

RESPONSIBLE PARTY

Name:	Caerus Oil and Gas	Phone:	(435) 790-9669
Address:	1368 S. 1200 E., Vernal, Utah 84078		

INCIDENT LOCATION

Incident Address:	Runway Liquid Transfer Line, Glen Bench Road		
Nearest Town:	OURAY	County:	UINTAH
Highway:		Mile Marker:	
UTM:	(E) 627528 (N) 4428255	Land Ownership:	SITLA

INCIDENT SUMMARY

A UDOGM inspector discovered production water flowing down the side of Glen Bench road. The fluid flowed to the north for approximately 1200 feet where it was contained by a dam put in in the draw to stop it. The company determined that the water transfer line from the Runway manifold disposal wells ruptured underground, which resulted in approximately 125 barrels of production water to be released along the road. The company was able to recover approximately 75 barrels of standing fluid.

CHEMICAL(S) REPORTED

Production Water 125 Barrels

IMPACTED MEDIA	Media	Media Other	Land Use	Waterway Name	Near Water	Distance	NRC Rpt. #
	Soils	N/A	Oil & Gas Production Field	N/A		N/A	N/A

NOTIFICATIONS MADE	Agency	Contact	Date	Time	By	Active?
	DWQ	Kevin Okleberry	7/21/2021	16:15	Reporting Party	Active
	DEQ DE	Nathan Hall	7/21/2021	16:15	Reporting Party	Active
	DOGM	Richard Powell	7/22/2021	08:05	kmo	Active
	SITLA	Tyson Todd	7/22/2021	08:05	kmo	Active
	Tri-County HD	Darrin Brown	7/22/2021	08:05	kmo	Active

ACTIONS TAKEN	Date	Agency	Action	Action Details
	6/26/2023	DWQ	Incident Closure	Resolved -

Incident notification reports are prepared by DEQ staff using information provided by the reporting party. The information is considered preliminary and is subject to revision. The reported incident and associated details may or may not be valid



Utah Department of Environmental Quality
Division of Environmental Response and Remediation
195 North 1950 West Salt Lake City, Utah 84116
Bus. Hours: 801-536-4100
Report Spills 24/7/365: 801-536-4123

Report Number 15057

ACTIONS TAKEN	Date	Agency	Action	Action Details
	7/22/2021	DWQ	DWQ No Enforcement	Evaluated incident, no DWQ enforcement.