

a. Input image & query



High-resolution inspection image
(sparse micro-evidence)




Is there anything dangerous in this image ? If so, tell me your advice.



b. AREP: ROI Proposal



Global context +
Local high-resolution crops



c. CTS: Continuity-Aware Token Selection



d. Grounded Output



Diagnosis

Foreign object detected near the conductor.



Advice

Remove the object and re-inspect the fitting area.




Cited reasoning

(Auditable answer)

Retrieved evidence(Top-2)



Foreign object near conductor may threaten safe clearance.



Remove debris and verify equipment integrity after handling.



ROI (candidate region)



Selected tokens



Unselected tokens



Pipeline flow



Output / reasoning



Model description