











Original Image		AI Detected Damages	Assessment Report		
 25 04 2022	 25 04 2022		Damage Parts	Damage Status	Repair Status
			Rear Bumper	Dent Medium, Dent Minor, Scratch	Repair
			Unidentified Panel	Scratch	Repair
			Medium		
 25 04 2022	 25 04 2022		Damage Parts	Damage Status	Repair Status
			Bonnet	Scratch	Repair
			Right Fender	Dent Minor, Scratch	Repair
			Minor		
 25 04 2022	 25 04 2022		Damage Parts	Damage Status	Repair Status
			Left Front Door	Dent Medium, Scratch	Repair
			Right Front Door	Dent Medium, Scratch	Repair
			Unidentified Panel	Dent Medium, Dent Minor, Scratch, Dent Major	Replace
			Major		





Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch	Repair
Front Grill	Scratch	Repair
Right Headlamp	Scratch	Replace
Right Fender	Dent Minor	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Front Bumper	Bumper Dent, Scratch	Repair
Bonnet	Scratch	Repair
Right Headlamp	Scratch	Replace
Unidentified Panel	Scratch	Repair
Medium		





Damage Parts	Damage Status	Repair Status
No Damage		





Damage Parts	Damage Status	Repair Status
Left Orvm	Scratch	Repair
Unidentified Panel	Dent Medium, Dent Minor, Scratch	Repair
Medium		



Damage Parts	Damage Status	Repair Status
Right Quarter Panel	Dent Minor	Repair
Right Rear Door	Scratch	Repair
Left Quarter Panel	Dent Minor	Repair
Left Front Door	Dent Medium	Repair
Unidentified Panel	Dent Medium	Repair
Medium		



Damage Parts	Damage Status	Repair Status
No Damage		



Damage Parts	Damage Status	Repair Status
Unidentified Panel	Dent Medium	Repair
Major		