Assessment Report

(Print Date: 27/06/2022, 05:36:47)



Original Image	Al Detected Damages	Assessment Report		
		Damage Parts	Damage Status	Repair Status
		Rear Bumper	Scratch	Repair
		Front Bumper	Scratch	Repair
		Minor		
		Damage Parts	Damage Status	Repair Status
		Front Bumper	Panel Gap	Repair
		Unidentified Panel	Dent Minor, Panel Gap	Repair
		Minor		
		Damage Parts	Damage Status	Repair Status
		No Damage		



