





Original Image		AI Detected Damages		Assessment Report		
		Damage Parts	Damage Status	Repair Status		
		No Damage				
		Damage Parts	Damage Status	Repair Status		
		Rear Bumper	Scratch	Repair		
		Minor				
		Damage Parts	Damage Status	Repair Status		
		Front Bumper	Bumper Replace	Replace		
		Unidentified Panel	Bumper Replace	Replace		
		Major				




Damage Parts	Damage Status	Repair Status
Right Fender	Bumper Replace	Replace
Front Bumper	Bumper Replace	Replace
Unidentified Panel	Panel Gap	Repair
Major		



Damage Parts	Damage Status	Repair Status
Left Front Door	Scratch	Repair
Unidentified Panel	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
No Damage		



Damage Parts	Damage Status	Repair Status
Right Fender	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Rear Bumper	Scratch	Repair
Major		



Damage Parts	Damage Status	Repair Status
Left Rear Door	Dent Minor	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch	Repair
Right Front Door	Scratch	Repair
Minor		