


Original Image	AI Detected Damages	Assessment Report		
		Damage Parts	Damage Status	Repair Status
		Unidentified Panel	Panel Gap	Repair
		Minor		
		Damage Parts	Damage Status	Repair Status
		Right Rear Door	Scratch	Repair
		Right Front Door	Dent Minor	Repair
		Right Quarter Panel	Scratch	Repair
		Unidentified Panel	Scratch	Repair
		Minor		
		Damage Parts	Damage Status	Repair Status
		Boot	Scratch	Repair
		Rear Bumper	Scratch, Bumper Dent	Repair
		Unidentified Panel	Scratch, Dent Minor	Repair
		Major		



Damage Parts	Damage Status	Repair Status
Right Front Door	Scratch	Repair
Right Fender	Panel Gap, Dent Major	Replace
Unidentified Panel	Bumper Replace	Replace
Major		



Damage Parts	Damage Status	Repair Status
Boot	Scratch	Repair
Rear Bumper	Bumper Replace	Replace
Right Quarter Panel	Scratch	Repair
Major		




Damage Parts	Damage Status	Repair Status
Front Bumper	Bumper Replace, Scratch	Replace
Right Fender	Dent Medium	Repair
Major		





Damage Parts	Damage Status	Repair Status
Right Front Door	Scratch, Dent Minor	Repair
Right Fender	Bumper Crack, Panel Gap, Scratch	Replace
Front Bumper	Bumper Crack, Scratch, Dent Minor	Replace
Unidentified Panel	Dent Medium	Repair
Medium		



Damage Parts	Damage Status	Repair Status
Unidentified Panel	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Boot	Scratch	Repair
Rear Bumper	Panel Gap, Bumper Replace	Replace
Unidentified Panel	Panel Gap, Scratch	Repair
Major		



Damage Parts	Damage Status	Repair Status
Rear Bumper	Scratch, Bumper Dent	Repair
Boot	Scratch	Repair
Left Quarter Panel	Scratch	Repair
Left Tail Lamp	Scratch	Replace
Unidentified Panel	Scratch	Repair
Medium		