




Original Image	AI Detected Damages	Assessment Report		
		Damage Parts	Damage Status	Repair Status
		Rear Bumper	Scratch	Repair
		Major		
		Damage Parts	Damage Status	Repair Status
		Front Bumper	Scratch	Repair
		Rear Bumper	Scratch	Repair
		Major		
		Damage Parts	Damage Status	Repair Status
		Left Front Door	Scratch	Repair
		Minor		




Damage Parts	Damage Status	Repair Status
Right Front Door	Scratch	Repair
Unidentified Panel	Scratch	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Left Fender	Dent Minor	Repair
Left Front Door	Scratch	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Boot	Dent Minor	Repair
Minor		




Damage Parts	Damage Status	Repair Status
Right Front Door	Scratch	Repair
Right Running Board	Scratch	Repair
Left Front Door	Scratch	Repair
Bonnet	Scratch	Repair
Unidentified Panel	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Front Bumper	Panel Gap, Bumper Replace	Replace
Bonnet	Scratch, Dent Medium	Repair
Front Grill	Scratch	Repair
Unidentified Panel	Bumper Replace	Replace
Major		



Damage Parts	Damage Status	Repair Status
Right Rear Door	Scratch	Repair
Right Front Door	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Unidentified Panel	Scratch	Repair
Minor		