




Original Image		AI Detected Damages	Assessment Report		
			Damage Parts	Damage Status	Repair Status
			Front Bumper	Panel Gap	Repair
			Bonnet	Scratch	Repair
			Minor		
			Damage Parts	Damage Status	Repair Status
			Front Bumper	Panel Gap, Scratch, Bumper Replace	Replace
			Major		
			Damage Parts	Damage Status	Repair Status
			Left Front Door	Scratch	Repair
			Minor		



Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch	Repair
Right Front Door	Scratch	Repair
Rear Bumper	Scratch	Repair
Right Rear Door	Scratch	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Bonnet	Dent Minor	Repair
Front Bumper	Panel Gap, Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Bonnet	Dent Medium, Dent Minor	Repair
Front Bumper	Panel Gap, Bumper Replace	Replace
Major		



Damage Parts	Damage Status	Repair Status
No Damage		



Damage Parts	Damage Status	Repair Status
Bonnet	Dent Minor	Repair
Front Bumper	Scratch, Dent Minor	Repair
Unidentified Panel	Panel Gap	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Boot	Scratch	Repair
Front Bumper	Scratch	Repair
Rear Bumper	Scratch	Repair
Bonnet	Scratch	Repair
Unidentified Panel	Scratch	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Rear Bumper	Scratch	Repair
Minor		