


Original Image	AI Detected Damages	Assessment Report		
		Damage Parts	Damage Status	Repair Status
		Front Bumper	Panel Gap, Scratch, Crack	Replace
		Right Headlamp	Crack, Scratch	Replace
		Unidentified Panel	Panel Gap	Repair
Medium				
		Damage Parts	Damage Status	Repair Status
		No Damage		
		Damage Parts	Damage Status	Repair Status
		Front Bumper	Bumper Crack, Panel Gap, Scratch, Bumper Dent	Replace
		Tyre	Scratch	Repair
		Front Grill	Scratch	Repair
		Unidentified Panel	Panel Gap, Dent Medium	Repair
Medium				



Damage Parts	Damage Status	Repair Status
Unidentified Panel	Dent Minor	Repair
Major		



Damage Parts	Damage Status	Repair Status
Right Rear Door	Scratch	Repair
Major		





Damage Parts	Damage Status	Repair Status
Left Front Door	Scratch	Repair
Left Rear Door	Scratch	Repair
Unidentified Panel	Dent Minor	Repair
Minor		




Damage Parts	Damage Status	Repair Status
No Damage		



Damage Parts	Damage Status	Repair Status
Front Bumper	Panel Gap, Scratch	Repair
Right Fender	Scratch	Repair
Unidentified Panel	Panel Gap	Repair
Minor		



Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch, Bumper Replace, Dent Minor, Bumper Crack, Panel Gap	Replace
Front Grill	Scratch	Repair
Unidentified Panel	Panel Gap, Dent Minor	Repair
Major		



Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch, Bumper Replace, Bumper Crack, Crack, Panel Gap	Replace
Tyre	Scratch	Repair
Front Grill	Scratch	Repair
Right Headlamp	Crack	Replace
Unidentified Panel	Panel Gap, Dent Minor	Repair
Major		