Assessment Report

(Print Date: 27/06/2022, 05:45:16)




Original Image	Al Detected Damages	Assessment Report		
	Jan Jan	Damage Parts	Damage Status	Repair Status
		Rear Bumper	Dent Minor, Scratch	Repair
		Boot	Dent Minor, Scratch	Repair
		Major		
	Damage Parts	Damage Status	Repair Status	
		Front Bumper	Scratch, Bumper Crack	Replace
		Rear Bumper	Scratch, Bumper Crack	Replace
		Unidentified Panel	Bumper Crack	Replace
		Major		
	Damage Parts	Damage Status	Repair Status	
			No Damage	








Damage Status	Repair Status			
Scratch, Bumper Crack	Replace			
Scratch	Repair			
Scratch, Bumper Crack	Replace			
Bumper Crack	Replace			
Major				
	Status Scratch, Bumper Crack Scratch Scratch, Bumper Crack Bumper Crack			





Damage Parts	Damage Status	Repair Status		
Front Bumper	Scratch	Repair		
Unidentified Panel	Dent Minor	Repair		
Minor				





Damage Parts	Damage Status	Repair Status		
Front Bumper	Scratch	Repair		
Bonnet	Scratch	Repair		
Right Front Door	Scratch	Repair		
Right Fender	Scratch, Bumper Crack	Replace		
Boot	Scratch	Repair		
Unidentified Panel	Bumper Crack Replace			
Major				