## Assessment Report

(Print Date: 30/06/2022, 12:39:25)



## **Original Image**









	<u> </u>	
Damage Parts	Damage Status	Repair Status
Boot	Dent Minor	Repair
Rear Bumper	Scratch, Dent Minor	Repair
Major		





Damage Parts	Damage Status	Repair Status
Rear Bumper	Scratch	Repair
Right Quarter Panel	Dent Minor	Repair
Front Bumper	Scratch	Repair
Major		






Damage Parts	Damage Status	Repair Status
Left Front Door	Scratch	Repair
Left Rear Door	Scratch, Dent Minor	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Right Front Door	Scratch, Dent Minor	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Left Front Door	Scratch	Repair
Left Fender	Dent Medium, Dent Minor	Repair
Left Running Board	Scratch	Repair
Left Rear Door	Dent Medium, Scratch, Dent Minor	Repair
Left Quarter Panel	Dent Medium, Dent Minor	Repair
Unidentified Panel	Dent Minor	Repair
Minor		






Damage Parts	Damage Status	Repair Status
Rear Bumper	Scratch	Repair
Boot	Dent Minor	Repair
Front Bumper	Scratch	Repair
Unidentified	Bumper	Poplaco
Panel	Replace	Replace
Major		





Damage Parts	Damage Status	Repair Status	
Right Front Door	Scratch	Repair	
Left Front Door	Scratch	Repair	
Unidentified Panel	Scratch	Repair	
	Minor		





Damage Parts	Damage Status	Repair Status	
Bonnet	Bumper Crack, Scratch, Dent Medium	Replace	
Front Bumper	Bumper Replace, Scratch, Bumper Dent	Replace	
Rear Bumper	Bumper Dent	Repair	
Front Grill	Crack, Scratch	Replace	
Right Headlamp	Crack	Replace	
Unidentified Panel	Bumper Crack, Bumper Replace, Dent Major	Replace	
Major			





Damage	Damage	Repair
Parts	Status	Status
No Damage		





	Damage Parts	Damage Status	Repair Status
j.	Rear Bumper	Scratch	Repair
9	Front Bumper	Scratch	Repair
		Major	