Assessment Report

(Print Date: 27/06/2022, 05:58:56)



Original Image

Al Detected Damages

Assessment Report






Damage Parts	Damage Status	Repair Status
Rear Bumper	Dent Minor, Dent Medium, Scratch, Bumper Crack	Replace
Unidentified Panel	Dent Medium, Dent Minor, Scratch	Repair
Major		





Damage Parts	Damage Status	Repair Status
Bonnet	Scratch	Repair
Right Fender	Dent Minor, Scratch	Repair
Right Quarter Panel	Dent Minor, Scratch	Repair
Boot	Dent Minor, Scratch	Repair
Left Fender	Dent Minor, Scratch	Repair
Left Quarter Panel	Dent Minor, Scratch	Repair
Unidentified Panel	Dent Medium	Repair
Minor		





Damage Parts	Damage Status	Repair Status
Left Front Door	Dent Minor, Scratch	Repair
Right Front Door	Dent Medium, Dent Minor, Scratch, Dent Major	Replace
Unidentified Panel	Dent Medium, Dent Minor, Scratch	Repair
Medium		





Damage Parts	Damage Status	Repair Status
Front Bumper	Scratch	Repair
Front Grill	Scratch	Repair
Right Fender	Dent Minor, Scratch	Repair
Right Headlamp	Scratch	Replace
Minor		





Damage Status	Repair Status	
Dent Minor, Scratch	Repair	
Bumper Dent, Scratch	Repair	
Scratch	Repair	
Bumper Dent, Bumper Crack	Replace	
Major		
	Dent Minor, Scratch Bumper Dent, Scratch Scratch Bumper Dent, Bumper Crack	





Damage	Damage	Repair
Parts	Status	Status
No Damage		






Damage Parts	Damage Status	Repair Status
Left Orvm	Scratch	Repair
Left Rear Door	Dent Medium, Dent Major	Replace
Left Front Door	Dent Minor, Scratch	Repair
Unidentified Panel	Dent Medium, Dent Minor, Scratch	Repair
Medium		





Damage Parts	Damage Status	Repair Status
Left Front Door	Dent Medium, Dent Minor	Repair
Left Quarter Panel	Dent Minor, Dent Medium	Repair
Left Rear Door	Scratch, Dent Major	Replace
Unidentified Panel	Dent Medium, Bumper Crack	Replace
Major		





Damage	Damage	Repair
Parts	Status	Status
No Damage		





Damage Parts	Damage Status	Repair Status
Unidentified Panel	Dent Medium, Dent Major	Replace
Major		