

VALUATION REPORT
SBI-style property valuation format

Reference No.	VAL-2026-0001	Date	09/08/2026
---------------	---------------	------	------------

VALUATION CERTIFICATE

This is to certify that the property situated at Sample Mouja, Sample Tehsil, Sample District, owned by Sample Land Owner, has been assessed from the approved information and documents available for this assignment. This report records unavailable information as N/A.

Owner: Sample Land Owner

Market value	Rs. 34,48,000.00
Book value	205000
Realisable value	Rs. 31,03,200.00
Distress sale value	Rs. 25,86,000.00

Declaration

The property particulars have been considered from supplied documents and approved input. Legal title, document authenticity, and statutory permissions require independent verification by the appropriate authority or legal adviser.

FORMAT OF VALUATION REPORT

(For property valuation assignments)

Name & address of branch	N/A
Name of customer(s) / borrower unit	Sample Borrower
Purpose of valuation	N/A
1.	Customer Details
Name of land owner	Sample Land Owner
Phone number	N/A
2.	Property Details
Address	Sample Mouja, Sample Tehsil, Sample District
Nearby landmark / map reference	N/A
3.	Document Details
Layout plan	N/A
Building plan	Available
Construction permission	N/A
Occupation permission	N/A
Sale deed(s)	I-0542 dated 24/08/2021
Khatiyani number	1879 & 1878
Agreement serial / date	N/A
N/A	Location of Property
RS / Hal plot number	3789/5799
CS / Sebek Dag number	N/A
Subdivision	Sample Subdivision
Revenue circle	Sample Circle
Tehsil	Sample Tehsil
Mouja	Sample Mouja
Classification of land	Bhiti

4.	Physical Details	
Adjoining properties	According to deed / agreement	According to site visit
North	Keshab Majumder	N/A
South	Swapan Sen	N/A
East	Hrishi Som	N/A
West	Road	N/A
Approach road	West / North-South	N/A
Matching of boundaries	N/A	N/A
Approved land use	N/A	
Type of property	N/A	
4A.	Dimension of Property	
North	N/A	
South	N/A	
East	N/A	
West	N/A	
N/A	Building / Site Details	
Number of rooms	N/A	
Number of floors	N/A	
Approx. age of property	8 years	
Type of structure	RCC	
Plinth area	800 sq ft	
5.	Tenure / Occupancy Details	
Status of tenure	N/A	
Number of years of occupancy	N/A	
Relationship of tenant / owner	N/A	
6.	Stage of Construction	
Stage of construction	N/A	
Extent of completion	N/A	
7.	Violations if any observed	
Nature and extent of violations	N/A	
8.	Area Details of the Property	
Site area	3456	
Built-up area	800 sq ft	
Carpet area	N/A	
Remarks	N/A	

9.	Valuation
-----------	------------------

Summary of Valuation

Guideline value	N/A
Prevailing market rate	N/A
Adopted rate of valuation	N/A
Estimated value of land	Rs. 15,55,200.00

Part A - Land

Land class	Area	Considered	Rate	Value
Bhiti	3456 sq ft	Yes	Rs. 450.00	Rs. 15,55,200.00
Estimated land value				Rs. 15,55,200.00

Part B - Building

Particulars	Plinth area	Age	Replacement cost	Depreciation	Net value
RCC	800 sq ft	8 years	Rs. 20,80,000.00	Rs. 1,87,200.00	Rs. 18,92,800.00
Total					Rs. 18,92,800.00

Parts C-F - Extra items, amenities, miscellaneous and services

Extra items	N/A
Amenities	N/A
Miscellaneous	N/A
Services	N/A

TOTAL ABSTRACT OF THE ENTIRE PROPERTY

Part A	Land	Rs. 15,55,200.00
Part B	Building	Rs. 18,92,800.00
Part C-F	Extra items, amenities, miscellaneous and services	N/A
N/A	Total market value	Rs. 34,48,000.00

Remarks

Sample report created for layout verification only.

This valuation is a technical opinion based on the information made available for the assignment. It does not verify title, authenticity, approvals, or legal encumbrances. Any unavailable field has been recorded as N/A.

1. Market Value	Rs. 34,48,000.00
2. Realisable Value	Rs. 31,03,200.00
3. Distress Sale Value	Rs. 25,86,000.00

Signature of Valuer

Authorised Valuer

KEY PLAN

Indicative only - not to scale - generated from confirmed valuation data

North: Keshab Majumder		
West: Road	CONCERN PROPERTY Khatian: 1879 & 1878 RS Hal: 3789/5799	East: Hrishi Som
South: Swapan Sen		
Approach road / direction: West / North-South		

Map coordinates, site photographs, and official cadastral maps must be attached separately when supplied and verified.

PHOTOGRAPHS AND EVIDENCE ANNEXURE

Property photographs	N/A - attach verified site photographs when available
Official cadastral / dag map	N/A - attach verified map when available
Extraction evidence	N/A
Document conflicts	None recorded

END OF REPORT