

■ VEHICLE HEALTH ANALYSIS REPORT

VEHICLE INFORMATION

Profile Name:	318840
Make:	Nissan
Model:	Altima
Year:	2017
VIN:	00000000000000
Report Date:	2025-11-12 19:29:39

HEALTH ANALYSIS SUMMARY

System	Health Score	Status	Issues
Engine System	85/100	■ Good	Normal operation
Battery System	75/100	■ Fair	Slight aging detected
Cooling System	90/100	■ Excellent	Optimal performance
Electrical System	80/100	■ Good	Minor fluctuations

MAINTENANCE RECOMMENDATIONS

1. Continue regular maintenance schedule
2. Check tire pressure monthly
3. Monitor fluid levels regularly
4. Follow manufacturer service intervals
5. Keep maintenance records updated