



SHEQ INSTALLATION SERVICE REPORT

DATE		DOCUMENT NO.		APPROVED BY	
26 May 2026		SHEQ-INST-01		Management	
CLIENT	ENGINEER(S)		DATE		AUDITOR
SITE ADDRESS			SERVICE MANAGER		
EQUIPMENT ID			SITE CONTACT		
Project Summary - Assessment of the project H&S status					
AMBER		☐ Installation Director ☐ SHEQ Advisor ☐ Principal Contractor			

SCORING SUMMARY & PERFORMANCE ANALYTICS

ITEM / SECTION	AVERAGE SCORE	MAXIMUM SCORE	% COMPLIANCE RATE
1.1 RISK ASSESSMENTS & METHOD STATEMENT (RAMS)	3.00	6	100%
1.2 REGISTERS	3.00	6	100%
1.3 INSPECTION RECORDS	3.00	9	100%
2.1 ACCESS / EGRESS TO POINT OF WORK	3.00	6	100%
2.2 LIGHTING	-	0	0%
2.3 WELFARE & ENVIRONMENT	-	0	0%
3.1 SUBCONTRACTORS ON SITE	-	0	0%
3.2 FOLLOWING CONTROL MEASURES	-	0	0%
4.1 POWER TOOLS	-	0	0%
4.2 BARRIERS	-	0	0%
4.3 HAND TOOLS	-	0	0%
5.1 LOLER	-	0	0%
5.2 MATERIAL STORAGE & DISPOSAL	-	0	0%
5.3 ELECTRICAL SAFETY	-	0	0%
5.4 SHAFT SAFETY	-	0	0%
5.5 MACHINERY GUARDING	-	0	0%
6.1 WORKING FROM WORK PLATFORMS	-	0	0%
6.2 LADDERS	-	0	0%
6.3 FALL PREVENTION	-	0	0%
7.1 SITE INDUCTION/REGISTRATION	-	0	0%
7.2 ON SITE NOTIFICATION	-	0	0%
7.3 ACCIDENT REPORTING	-	0	0%
7.4 COMPETENCE & TRAINING	-	0	0%
7.5 SECURITY & FIRE	-	0	0%
8.1 ENTRANCE PROTECTION	-	0	0%
8.2 PERSONAL PROTECTIVE EQUIPMENT	-	0	0%
8.3 SAFETY GEAR/PIT PROPS	-	0	0%
8.5 TWO WAY COMMUNICATION	-	0	0%
OVERALL COMPLIANCE RATE:			100%

Sectional Performance Analytics

■ High
 ■ Action Needed
 ■ Critical

1.1 RISK ASSESSMENTS & METHOD STATEMENT (RAMS)		100%
1.2 REGISTERS		100%
1.3 INSPECTION RECORDS		100%
2.1 ACCESS / EGRESS TO POINT OF WORK		100%
2.2 LIGHTING		0%
2.3 WELFARE & ENVIRONMENT		0%
3.1 SUBCONTRACTORS ON SITE		0%
3.2 FOLLOWING CONTROL MEASURES		0%
4.1 POWER TOOLS		0%
4.2 BARRIERS		0%
4.3 HAND TOOLS		0%
5.1 LOLER		0%
5.2 MATERIAL STORAGE & DISPOSAL		0%
5.3 ELECTRICAL SAFETY		0%
5.4 SHAFT SAFETY		0%
5.5 MACHINERY GUARDING		0%
6.1 WORKING FROM WORK PLATFORMS		0%
6.2 LADDERS		0%
6.3 FALL PREVENTION		0%
7.1 SITE INDUCTION/REGISTRATION		0%
7.2 ON SITE NOTIFICATION		0%
7.3 ACCIDENT REPORTING		0%
7.4 COMPETENCE & TRAINING		0%
7.5 SECURITY & FIRE		0%
8.1 ENTRANCE PROTECTION		0%
8.2 PERSONAL PROTECTIVE EQUIPMENT		0%
8.3 SAFETY GEAR/PIT PROPS		0%
8.5 TWO WAY COMMUNICATION		0%

ITEM	SCORE	Comments
1 Non-compliant 2 Partial 3 Full Compliance N/A NIU		
1. PROJECT DOCUMENTATION		
1.1 RISK ASSESSMENTS & METHOD STATEMENT (RAMS)		
RAMS in place	3	
Evidence of communication available	3	
1.2 REGISTERS		
Equipment register	NIU	
PPE/PAT/FIRST AID/ FIRE MARSHAL	3	
1.3 INSPECTION RECORDS		
Hoardings / Entrance protection inspections	3	
Scaffold inspections	NIU	
Tirak inspections	NIU	
TOTAL SCORE	21 / 21	
2. SITE CONDITIONS		
2.1 ACCESS / EGRESS TO POINT OF WORK		
Safe conditions	3	
Emergency escape routes clear at all times	3	
2.2 LIGHTING		
General lighting		
Access routes lighting		
Task lighting		
2.3 WELFARE & ENVIRONMENT		
Canteen and rest room		
Toilets and washing facilities		
First aid facilities		
Notices and Statutory signs		
Working climate ie dust/noise/vibration etc		
TOTAL SCORE	6 / 6	
3. SUB CONTRACTORS		
3.1 SUBCONTRACTORS ON SITE		
Name and Trade of Sub Contractors on Site		
Sub Contractors Relevant qualifications kept on		
Subcontractors working to MS-RA		
3.2 FOLLOWING CONTROL MEASURES		
Knowledge of risks/controls in place?		
TOTAL SCORE	0 / 0	

4. TOOLS AND EQUIPMENT**4.1 POWER TOOLS**

Fit for purpose and have been tested (PAT)?

4.2 BARRIERS

Suitable and fit for purpose?

Correctly used?

4.3 HAND TOOLS

Suitable and fit for purpose?

Tools correctly used?

TOTAL SCORE**0 / 0****5. LIFT EQUIPMENT & INSTALLATION****5.1 LOLER**

Lifting equipment inspection/certification

Lifting accessories inspection/certification

Weekly / daily inspections of equipment

5.2 MATERIAL STORAGE & DISPOSAL

Materials stored correctly

Waste material disposed appropriately

Tool Box gas struts in good working conditions

5.3 ELECTRICAL SAFETY

Signage & tagging available?

Condition of Test Equipment / calibration

5.4 SHAFT SAFETY

Working inside machine room

Working inside the lift shaft

Crash deck inspected and scaff tag signed off?

Openings around guide rails sealed

Working platform safe with handrails, midrails and

Drawbridge in place of working platform

Openings between landing doors and platform

Working outside lift shaft

5.5 MACHINERY GUARDING

Fitted/compliant with current standards?

TOTAL SCORE**0 / 0**

6. WORKING AT HEIGHTS		
6.1 WORKING FROM WORK PLATFORMS		
Guard rails in place: main & intermediate		
Toeboards in place		
6.2 LADDERS		
Fit for purpose		
Correctly positioned and secured		
6.3 FALL PREVENTION		
Harness / Teether belts		
Inspection records		
TOTAL SCORE	0 / 0	

7. GENERAL		
7.1 SITE INDUCTION/REGISTRATION		
Site specific induction		
Fujitec Induction		
Both Induction records maintained on file		
7.2 ON SITE NOTIFICATION		
Client aware of presence on site - swipe in or		
7.3 ACCIDENT REPORTING		
Accident Reporting Procedure in place		
7.4 COMPETENCE & TRAINING		
Technical/Tool Box Talks		
CSCS		
7.5 SECURITY & FIRE		
Site Security Level		
Fire Hazards		
Extinguishers		
Call Points		
Fire signage and Information		
TOTAL SCORE	0 / 0	

8. SAFETY ESSENTIALS		
8.1 ENTRANCE PROTECTION		
Hoardings safe with locks in place		
Signs in place for all hoardings		
8.2 PERSONAL PROTECTIVE EQUIPMENT		
Worn at all times		
Correct PPE being used for task		
Condition of PPE		
8.3 SAFETY GEAR/PIT PROPS		
Functioning as required		
Tested prior to starting installation		
8.5 TWO WAY COMMUNICATION		
In use when required/appropriate?		
TOTAL SCORE	0 / 0	

OTHER COMMENTS/OBSERVATIONS

OTHER CONTRACTORS

TOTAL SCORE	27 / 27	
-------------	---------	--

PHOTOS / DOCUMENTS

INSPECTOR'S FINAL COMMENTS / SUMMARY

OVERALL COMPLIANCE SCORE

COMPLIANCE RATE

100%

EXCELLENT COMPLIANCE

Total Rating Points: 27

Actual Points Scored: 27

SIGNATURE