

PERFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.

Memo No:- 49/AE/MNH/PHE/21-22

Date:- 15/7/2021

It is certified that an inspection team headed Phupu Dawa Bhusia (R.I.) (Name of officers with designation) from PHE Mangon (Name of Department Officer) inspected the Mangon Sr. Sec. School North Sikkim (Name & Address of the school) on 15/7/2021

And found that the supply of safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition of the school building & the campus as per the norms prescribed by the central/State/UT/Government.

The above valid for a period of one year



Signature with seal
Revenue Inspector
Public Health Engineering Department
Government of Sikkim
Mangon, North District
Name Phupu Dawa Bhusia
Designation R.I. PHE Dept

TO

The Govt. Sr. Sec.
School Mangon(N)
(Name & Address of the Institution)