

Test_Facility_Robot_UK



Executive Summary

BeaconMedaes Service Technician Robot_UK Tester tested the Medical Gas Pipeline System indicated by this report in accordance with HTM - Part B section (Maintenance) and/or accordance with the facilities own specification (where requested) and other applicable standards or agencies. The tests performed on this system were found to be within test specifications unless otherwise noted. The results, dates and locations of the tests performed and specific data on each test can be found on the Test Summary pages.

The testing of this system may include all or part of the tests offered by BeaconMedaes. Only the tests indicated by the summary and data pages were performed on the dates indicated. The results of the tests reported represent BeaconMedaes findings on the dates and locations indicated by the report forms only. System components include:

1. Outlet : 2 pcs

Informational Comments

The following comments are for informational purposes only and do not affect the overall code compliance of medical gas systems/components at this facility.

Count	Date	Logged By	Text
1		Robot_UK Tester	Both Toggles are disabled

Deficiencies

Additional Deficiencies

Count	Date	Logged By	Text
1		Robot_UK Tester	IS DEFICIENCY Toggle is enabled



Inspection Report

OUTLET

#	Test Date	Location	Product	Outlet condition is acceptable	Mechanical function is acceptable	Gas specificity is correct	Outlet does not leak	Flow and pressure drop is acceptable
1		Floor 1	Outlet: Other: BeaconMedaes: : 1ST FIX TU STUB MM N2O	Pass	Pass	Pass	Pass	Pass
2		Floor 1	Outlet: Other: BeaconMedaes: : 1ST FIX TU STUB MM N2O	Pass	Pass	Pass	Pass	Pass





AGSS Outlet . Flow at 1kPa	AGSS Outlet. Flow at 2kPa	AGSS Outlet. Flow at 4kPa	Risk assessment
			I am OK to commence works
			I am OK to commence works



Authorization to carry out work with/without an order number.

Notes: Customer will agree to supply Test Automatic UK with a valid order number or payment for non-account holders for the actual time spend, traveling and parts used during the breakdown intervention by next working day.

Customer Confirmation

Service Engineer Confirmation

|

|

Signed by Robot_UK

(Being duly authorized to sign on behalf of the customer)

Signed by Robot_UK Tester





Test_Facility_Robot_UK

