

Site Inspection Report (Sample)

The inspection of the test warehouse took place on schedule.

All fire exits were clear and the alarms were working.

Two shelving units need new safety labels.

Recommendations

Replace the safety labels on both shelving units.

Repeat the inspection within the next quarter.