Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-955336
Estimate date:	18 Apr 2023
Customer:	Louis White
Phone:	346-555-3950
Insurance claim:	C-1019
Vehicle:	2012 Nissan Altima
VIN:	729R8MDK8AU587355
License plate:	386 5ZG

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$555.57
Left quarter panel	1	$513.94
Headlamp assembly	1	$343.89
Body labor	16.7 hrs	$1,133.68
Paint and materials		$675.56
TOTAL		$3,222.64