Riley Auto Repair

500 Shaw Walk
Pearland, TX
Phone 713-555-8121

Repair Estimate

Estimate number:	EST-696575
Estimate date:	2025-04-10
Customer:	Gina Wells
Phone:	281-555-8404
Insurance claim:	C-1022
Vehicle:	2017 Jeep Cherokee
VIN:	M6LCUTDV099K17805
License plate:	36LK6

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$571.83
Hood panel	1	$606.82
Headlamp assembly	1	$502.68
Body labor	19.2 hrs	$1,308.94
Paint and materials		$570.10
TOTAL		$3,560.37