Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-783631
Estimate date:	12-24-24
Customer:	Ashley Miranda
Phone:	346-555-2717
Insurance claim:	C-1035
Vehicle:	2014 Jeep Cherokee
VIN:	89Y6ME5M8EEG86686
License plate:	115931

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$645.78
Left quarter panel	1	$703.47
Hood panel	1	$469.55
Body labor	17.8 hrs	$1,207.18
Paint and materials		$558.52
TOTAL		$3,584.50