Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-547035
Estimate date:	2023-04-25
Customer:	Todd Sanders
Phone:	346-555-2015
Insurance claim:	C-1038
Vehicle:	2014 Kia Sorento
VIN:	6WRHVP184ZE2X1117
License plate:	XDZ 926

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$955.93
Front bumper cover	1	$535.12
Headlamp assembly	1	$616.30
Body labor	23.6 hrs	$1,606.17
Paint and materials		$882.77
TOTAL		$4,596.29