Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-447852
Estimate date:	July 9, 2023
Customer:	Pamela Mosley
Phone:	713-555-9700
Insurance claim:	C-1058
Vehicle:	2017 Ford F-150
VIN:	2RX3JA0W30AZM1133
License plate:	60E-KJLT

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$703.86
Front bumper cover	1	$612.45
Left front fender	1	$467.39
Body labor	14.3 hrs	$971.02
Paint and materials		$493.59
TOTAL		$3,248.31