Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-352935
Estimate date:	13 Mar 2023
Customer:	Maria Burgess
Phone:	713-555-2125
Insurance claim:	C-1105
Vehicle:	2011 Toyota Camry
VIN:	RJBH9LTE0JGVG3432
License plate:	LSL-587

Estimate details

Description	Qty / Hours	Amount
Headlamp assembly	1	$711.46
Hood panel	1	$501.72
Right front door shell	1	$492.82
Body labor	19.5 hrs	$1,323.09
Paint and materials		$537.55
TOTAL		$3,566.64