Gilbert Auto Repair

6945 Mariah Corners Suite 737
Conroe, TX
Phone 832-555-0752

Repair Estimate

Estimate number:	EST-278988
Estimate date:	December 15, 2024
Customer:	Jose Reynolds
Phone:	
Insurance claim:	C-1205
Vehicle:	2020 Chevrolet Malibu
VIN:	VDG7SX709B51A7782
License plate:	798213

Estimate details

Description	Qty / Hours	Amount
Hood panel	1	$532.93
Right front door shell	1	$476.31
Front bumper cover	1	$277.13
Body labor	12.3 hrs	$835.69
Paint and materials		$509.92
TOTAL		$2,631.98