Ross Collision Center

5868 Crosby Crescent
Katy, TX
Phone 281-555-9401

Repair Estimate

Estimate number:	EST-164642
Estimate date:	16 May 2024
Customer:	Emily Moyer
Phone:	346-555-3638
Insurance claim:	C-1206
Vehicle:	2011 Kia Sorento
VIN:	S8WX4SYF3P1R06820
License plate:	35FF5

Estimate details

Description	Qty / Hours	Amount
Front bumper cover	1	$1,584.77
Left quarter panel	1	$1,186.72
Headlamp assembly	1	$907.65
Body labor	40.8 hrs	$2,773.36
Paint and materials		$2,008.42
TOTAL		$8,460.92