Hoffman Auto Body

280 Aguilar Drive
Conroe, TX
Phone 281-555-0450

Repair Estimate

Estimate number:	EST-528465
Estimate date:	2024-10-02
Customer:	Tyler Willis
Phone:	346-555-2879
Insurance claim:	C-1230
Vehicle:	2016 Ford F-150
VIN:	DT7EDXT10GLZ75230
License plate:	0YW2544

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$948.23
Headlamp assembly	1	$967.35
Front bumper cover	1	$773.87
Body labor	21.5 hrs	$1,460.79
Paint and materials		$774.92
TOTAL		$4,925.16