Carlson Collision Center

9816 Jonathan Station Suite 088
Sugar Land, TX
Phone 832-555-6159

Repair Estimate

Estimate number:	EST-988654
Estimate date:	12-30-23
Customer:	Danny Galloway
Phone:	713-555-1986
Insurance claim:	C-1240
Vehicle:	2024 Toyota Camry
VIN:	SADBZ4DA21BEB2101
License plate:	8AC6766

Estimate details

Description	Qty / Hours	Amount
Left quarter panel	1	$929.02
Front bumper cover	1	$763.97
Left front fender	1	$609.42
Body labor	19.9 hrs	$1,354.77
Paint and materials		$850.59
TOTAL		$4,507.77